



Your AutoCheck Vehicle History Report

Report Run Date: August 23, 2017 12:34:58 AM EDT

1999 Volkswagen Passat GLS

VIN: WVWMA63B3XE516428

Year: 1999

Make: Volkswagen

Model: Passat GLS

Style/Body: Sedan 4D

Class: Mid Range Car - Premium

Engine: 1.8L I4 MPI

Country of Assembly: Germany

Vehicle Age: 18 year(s)

Calculated Owners: 3



Accident Check
Reported accidents: 0



State Title Brand and Other Problem Check
Your vehicle checks out:



Odometer Check
Your vehicle checks out:
Last Reported Odometer Reading: 109,275



Vehicle Use and Event Check
Specific vehicle use(s) or events reported

This vehicle's AutoCheck Score



The AutoCheck Score is a summary of your vehicle's history. It lets you compare similar vehicles with ease.

This vehicle is eligible for Buyback Protection



Due to the vehicle's history showing no reported major state title brands, About Buyback Protection

(<https://www.autocheck.com/members/culdesac/whatIsThis.jsp>)

Accident Check

Not all accidents / issues are reported to AutoCheck.

Your Vehicle Checks Out: There have been no accidents reported to AutoCheck (<http://www.autocheck.com/terms>) for this 1999 Volkswagen Passat GLS (WVWMA63B3XE516428). AutoCheck receives its accident data from government sources and independent agencies, and based on the information available to us, we have found that no accidents have been reported on this vehicle.



State Title Brand and Other Problem Check



Your Vehicle Checks Out: AutoCheck's database for this 1999 Volkswagen Passat GLS (WVWMA63B3XE516428) shows no negative titles or other problems. When reported to AutoCheck (<http://www.autocheck.com/terms>), these events can indicate serious past damage or other significant problems. Check the Vehicle Use and Event Check for reported accidents that can affect vehicle safety and value.

**0 Problem(s)
Reported:**

15 State Title and Other Problem areas checked:

	No abandoned record
	No damaged or major damage incident record
	No fire damaged record
	No grey market record
	No hail damage record
	No insurance loss or probable total loss record
	No junk or scrapped record
	No manufacturer buyback or lemon record
	No odometer problem record
	No rebuilt or rebuildable record
	No salvage or salvage auction record
	No water damaged record
	No NHTSA crash test record
	No frame or structural damage record
	No recycling facility record

Odometer Check



Your Vehicle Checks Out: AutoCheck examined the reported odometer readings reported to AutoCheck (<http://www.autocheck.com/terms>) for this 1999 Volkswagen Passat GLS (WVWMA63B3XE516428) and no indication of an odometer rollback or tampering was found. AutoCheck uses business rules to determine if reported odometer readings are significantly less than previously reported values. Not all reported odometer readings are used. Title and auction events also report odometer tampering or breakage.

**0 Problem(s)
Reported:**

Mileage

Date Reported

	24	10/26/1999
	38,173	06/20/2001
	38,181	06/26/2001
	89,000	09/29/2011
	104,541	01/20/2017
	109,275	05/10/2017

Vehicle Use and Event Check

Information Reported: AutoCheck shows additional vehicle uses or events reported to AutoCheck (<http://www.autocheck.com/terms>) for this 1999 Volkswagen Passat GLS (WVWMA63B3XE516428). This includes reported vehicle uses such as rental or lease, and events such as whether the vehicle has been reported to have had a loan/lien or a duplicate title issued. Other events show if the vehicle has a reported accident and how many calculated accidents or if it has been reported stolen or repossessed. It is recommended to have pre-owned vehicles inspected by a third party prior to purchase.

**1 Event(s)
Reported:**
6 Vehicle uses checked:

	Fleet, rental and/or lease use record(s)
	No taxi use record
	No police use record
	No government use record
	No livery use record
	No driver education record

**2 Event(s)
Reported:**
9 Vehicle events checked:

	No accident record reported through accident data sources
	No corrected title record
	No duplicate title record
	Emission/safety inspection record(s)
	Loan/Lien record(s)
	No fire damage incident record
	No repossessed record
	No theft record
	No storm area registration/title record

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order. Any discrepancies will be in bold text.

Report Run Date August 23, 2017 12:34:58 AM EDT

Vehicle: 1999 Volkswagen Passat GLS (WVWMA63B3XE516428)



Event date	Location	Odometer reading	Data Source	Details
10/26/1999	CA	24	Motor Vehicle Dept.	ODOMETER READING FROM DMV
11/18/1999	OCEANSIDE, CA		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL (Leased Vehicle)
11/28/1999	CA		Motor Vehicle Dept.	TITLE (Lien Reported)
06/20/2001	CA	38,173	State Agency	PASSED EMISSION INSPECTION
06/26/2001	CA	38,181	Motor Vehicle Dept.	ODOMETER READING FROM DMV

08/17/2001	ESCONDIDO, CA		Motor Vehicle Dept.	TITLE REGISTRATION EVENT/RENEWAL
09/29/2011	SARASOTA, FL	89,000	Motor Vehicle Dept.	TITLE (Title #:0107263838)
09/29/2011	SARASOTA, FL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
04/16/2012	SARASOTA, FL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
04/12/2013	SARASOTA, FL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
05/12/2014	SARASOTA, FL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
04/15/2015	SARASOTA, FL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
03/15/2016	SARASOTA, FL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
01/20/2017	FL	104,541	Auto Auction	REPORTED AT AUTO AUCTION
05/10/2017	FL	109,275	Motor Vehicle Dept.	ODOMETER READING FROM DMV
05/10/2017	STUART, FL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
05/18/2017	STUART, FL		Motor Vehicle Dept.	TITLE (Title #:0107263838)

This Vehicle's Glossary

Below are the specific definitions for events that appear in this vehicle's report.

More information is available in the full AutoCheck glossary. (https://www.autocheck.com/members/culdesac/freelink_glossary.jsp)

Term	Section Location	Definition
Loan/Lien	Vehicle Use and Event Check	A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.
Emission/Safety Inspection	Vehicle Use and Event Check	An approved emission testing station has inspected the vehicle to measure the amount of pollutants the vehicle emits into the environment.
Fleet, Rental and/or Lease Use	Vehicle Use and Event Check	The vehicle has been reported as used as a fleet, rental, and/or lease vehicle.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to AutoCheck Terms and Conditions . If you obtained the report from a dealer, the dealer has been provided with these Terms & Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 955 American Lane Schaumburg IL 60173

Buyback Protection Terms and Conditions

This vehicle (WVWMA63B3XE516428) qualifies for AutoCheck Buyback Protection . If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbp/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 955 American Lane Schaumburg IL 60173

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.